

TREE DISPOSITION PLAN							
No.	SCIENTIFIC NAME	COMMON NAME	D.B.H.	HEIGHT	SPREAD	MITIGATION	DISPOSITION
			(Inches)	(Feet)	(Feet)	(Sq. Feet)	
1	Bursera simaruba	Gumbo limbo	9	18	18		To Remain
2	Ficus benjamina	Weeping fig	16	20	25	490.63	To Be Removed - in way of const.
3	Coccoloba uvifera	Seagrape	42"	25'	33	1,709.73	To Be Removed - in way of const.
4	Delonix regia	Royal poinciana	18"	30'	38	2,267.08	To Be Removed - in way of const.
5	Manilkara bidentata	Balata	37"	28'	35	N/A	To Be Removed - Prohibited
6	Bursera simaruba	Gumbo limbo	9"	18'	20	314.00	To Be Removed - in way of const.
7	Quercus laurifolia	Laurel oak	17"	25'	25	490.63	To Remain
8	Bucida buceras	Black olive	19"	35'	45	3,179.25	To Be Removed - in way of const.
9	Delonix regia	Royal poinciana	15"	45'	38	1,133.54	To Be Removed - in way of const.
10	Ficus benjamina	Weeping fig	15"	35'	22	379.94	To Be Removed - in way of const.
11	Bucida buceras	Black olive	9"	25'	28	615.44	To Be Removed - in way of const.
12	Bucida buceras	Black olive	12"	35'	38	1,133.54	To Be Removed - in way of const.
12A	Coccoloba uvifera	Seagrape	14"	18'	15	176.63	To Be Removed - in poor condition
13	Quercus laurifolia	Laurel oak	17"	35'	36	1,017.36	To Be Removed - in way of const.
14	Quercus laurifolia	Laurel oak	21"	35'	45	3,179.25	To Be Removed - in way of const.
15	Ficus benjamina	Weeping fig	48"	30'	50	1,962.50	To Be Removed - Never specimen
16	Syzygium cumini	Jambolan	21"	30'	48	3,617.28	To Be Removed - in way of const.
17	Coccoloba uvifera	Seagrape	87"	35'	50	3,925.00	To Remain
17A	Azadiracta indica	Neem	7"	16'	10	78.50	To Be Removed -poor condition
18	Leucaena leucocephala	Lead tree	14"	28'	18	N/A	To Be Removed - Prohibited
19	Bucida buceras	Black olive	12"	25'	33	854.87	To Remain
20	Bucida buceras	Black olive	12"	28'	28		To Remain
21	Bursera simaruba	Gumbo limbo	21"	25'	27'		To Relocate within property limits
22	Araucaria heterophylla	Norfolk Island pine	14"	28'	14	N/A	To Be Removed - Prohibited
22A	Juniperus chinensis	Chinese juniper	5"	16'	9	63.59	To Be Removed - in way of const.
22B	Mimusops elengi	Spanish cherry	6"	14'	12	113.04	To Be Removed - in way of const.
23	Pongamia pinnata	Pongam	17"	25'	34	907.46	To Be Removed - in way of const.
24	Mimusops elengi	Spanish cherry	7"	18'	14	153.86	To Be Removed - in way of const.
25	Bucida buceras	Black olive	27"	35'	38	2,267.08	To Be Removed - in way of const.
26	Mimusops elengi	Spanish cherry	7"	18'	16	200.96	To Be Removed - in way of const.
27	Schefflera actinophylla	Umbrella tree	41"	20'	18	N/A	To Be Removed - Prohibited
28	Bucida buceras	Black olive	21"	35'	34	1,814.92	To Be Removed - in way of const.
29	Ficus benjamina	Weeping fig	6"	22'	14	153.86	To Be Removed - in way of const.
29A	Adonidia merrillii	Christmas palm	5"	16'	8	50.24	To Be Removed - in way of const.
30	Ficus benjamina	Weeping fig	14"	30'	28	615.44	To Be Removed - Never specimen
31	Ficus benjamina	Weeping fig	20"	30'	25	490.63	To Be Removed - Never specimen
32	Adonidia merrillii	Christmas palm	5"	10'	10	78.50	To Be Removed - in way of const.
33	Ficus benjamina	Weeping fig	9"	25'	12	113.04	To Be Removed - in way of const.
34	Araucaria heterophylla	Norfolk Island pine	10"	30'	9	N/A	To Be Removed - Prohibited
35	Ficus benjamina	Weeping fig	21"	30'	35	961.63	To Be Removed - Never specimen
36	Quercus laurifolia	Laurel oak	12"	24'	12	113.04	To Be Removed - in way of const.
37	Ficus benjamina	Weeping fig	17"	20'	28	615.44	To Be Removed - Never specimen
38	Ficus benjamina	Weeping fig	15"	25'	30	706.50	To Be Removed - Never specimen
38A	Ficus benjamina	Weeping fig	3"	15'	8	50.24	To Be Removed - Never specimen
39	Swietenia mahagoni	Mahogany	16"	35'	34	907.46	To Be Removed - in way of const.
40	Ficus benjamina	Weeping fig	20"	22'	15	176.63	To Be Removed - Never specimen
41	Ficus benjamina	Weeping fig	6"	25'	12	113.04	To Be Removed - Never specimen
42	Ficus benjamina	Weeping fig	18"	35'	20	314.00	To Be Removed - Never specimen
43	Ficus benjamina	Weeping fig	35"	35'	15	176.63	To Be Removed - Never specimen
43A	Adonidia merrillii	Christmas palm	6"	20'	10	78.50	To Be Removed - in way of const.
44	Ficus aurea	Strangler fig	20"	25'	28	1,230.88	To Be Removed - in way of const.
45	Ficus benjamina	Weeping fig	31"	18'	8	50.24	To Be Removed - Never specimen
46	Schefflera actinophylla	Umbrella tree	13"	18'	14	N/A	To Be Removed - Prohibited
47	Schefflera actinophylla	Umbrella tree	25"	18'	16	N/A	To Be Removed - Prohibited
48	Syzygium cumini	Jambolan	65"	45'	60	5,652.00	To Be Removed - in way of const.
49	Syzygium cumini	Jambolan	18"	25'	45	3,179.25	To Be Removed - in way of const.
49A	Ptychosperma elegans	Solitare palm	3"	25'	6	28.26	To Be Removed - in way of const.
49B	Ptychosperma elegans	Solitare palm	3"	16'	6	28.26	To Be Removed - in way of const.
49C	Ptychosperma elegans	Solitare palm	3"	25'	7	38.47	To Be Removed - in way of const.
50	Ficus benjamina	Weeping fig	30"	25'	30	706.50	To Be Removed - Never specimen

TREE DISPOSITION LEGEND

No.	SCIENTIFIC NAME	COMMON NAME	D.B.H.	HEIGHT	SPREAD	MITIGATION	DISPOSITION
			(Inches)	(Feet)	(Feet)	(Sq. Feet)	
51	Bucida buceras	Black olive	20"	30'	55	4,749.25	To Be Removed - in way of const.
52	Ficus benjamina	Weeping fig	19"	30'	25	490.63	To Be Removed - Never specimen
53	Ficus benjamina	Weeping fig	8"	30'	25	490.63	To Be Removed - in way of const.
54	Coccoloba uvifera	Seagrape	20"	25'	35	1,923.25	To Be Removed - in way of const.
55	Coccoloba uvifera	Seagrape	12"	25'	18		To Remain
56	Syzygium cumini	Jambolan	49"	35'	35	1,923.25	To Be Removed - in way of const.
57	Bursera simaruba	Gumbo limbo	10"	17'	8	50.24	To Be Removed - in way of const.
58	Quercus laurifolia	Laurel oak	22"	35'	38	2,267.08	To Be Removed - in way of const.
59	Bursera simaruba	Gumbo limbo	9"	28'	30	706.50	To Be Removed - in way of const.
60	Quercus laurifolia	Laurel oak	9"	28'	15	176.63	To Be Removed - in way of const.
61	Quercus laurifolia	Laurel oak	9"	28'	18	254.34	To Be Removed - in way of const.
62	Quercus laurifolia	Laurel oak	16"	35'	35	961.63	To Be Removed - in way of const.
63	Quercus laurifolia	Laurel oak	11"	18'	20	314.00	To Be Removed - in way of const.
64	Quercus laurifolia	Laurel oak	12"	30'	24	452.16	To Be Removed - in way of const.
65	Quercus laurifolia	Laurel oak	6"	30'	34	907.46	To Be Removed - in way of const.
66	Quercus laurifolia	Laurel oak	16"	28'	34	907.46	To Be Removed - in way of const.
67	Quercus laurifolia	Laurel oak	25"	22'	24	904.32	To Be Removed - in way of const.
68	Quercus laurifolia	Laurel oak	16"	20'	15	176.63	To Be Removed - in way of const.
69	Quercus laurifolia	Laurel oak	26"	25'	30	1,413.00	To Be Removed - in way of const.
70	Bursera simaruba	Gumbo limbo	6"	22'	12	113.04	To Be Removed - in way of const.
71	Blighia sapida	Ackee	6"	16'	20	314.00	To Be Removed - in way of const.
72	Bursera simaruba	Gumbo limbo	16"	12'	15	176.63	To Be Removed - in way of const.
73	Quercus laurifolia	Laurel oak	9"	30'	18	254.34	To Be Removed - in way of const.
73A	Bursera simaruba	Gumbo limbo	3"	14'	10	78.50	To Be Removed - in way of const.
74	Quercus laurifolia	Laurel oak	11"	30'	25	490.63	To Be Removed - in way of const.
74A	Quercus laurifolia	Laurel oak	22"	30'	30	1,413.00	To Be Removed - in way of const.
75	Quercus laurifolia	Laurel oak	10"	28'	22	379.94	To Be Removed - in way of const.
76	Quercus laurifolia	Laurel oak	21"	28'	25	981.25	To Be Removed - in way of const.
77	Quercus laurifolia	Laurel oak	8"	22'	30	706.50	To Be Removed - in way of const.
78	Bursera simaruba	Gumbo limbo	24"	15'	16	401.92	To Be Removed - in way of const.
79	Bursera simaruba	Gumbo limbo	10"	13'	12	113.04	To Be Removed - in way of const.
80	Bursera simaruba	Gumbo limbo	9"	17'	23	415.27	To Be Removed - in way of const.
81	Bursera simaruba	Gumbo limbo	23"	18'	20	628.00	To Be Removed - in way of const.
82	Bursera simaruba	Gumbo limbo	15"	18'	22	379.94	To Be Removed - in way of const.
83	Bursera simaruba	Gumbo limbo	14"	18'	26	530.66	To Be Removed - in way of const.
84	Bursera simaruba	Gumbo limbo	17"	18'	28	615.44	To Be Removed - in way of const.
85	Bursera simaruba	Gumbo limbo	18"	22'	23	830.53	To Be Removed - in way of const.
86	Bursera simaruba	Gumbo limbo	12"	14'	12	113.04	To Be Removed - in way of const.
87	Bursera simaruba	Gumbo limbo	13"	18'	24	452.16	To Be Removed - in way of const.
88	Bursera simaruba	Gumbo limbo	7"	14'	18	254.34	To Be Removed - in way of const.
89	Bursera simaruba	Gumbo limbo	6"	12'	12	113.04	To Be Removed - in way of const.
89A	Bursera simaruba	Gumbo limbo	5"	14'	12	113.04	To Be Removed - in way of const.
90	Bursera simaruba	Gumbo limbo	12"	20'	18	254.34	To Be Removed - in way of const.
91	Bursera simaruba	Gumbo limbo	13"	22'	25	490.63	To Be Removed - in way of const.
92	Bursera simaruba	Gumbo limbo	8"	20'	18	254.34	To Be Removed - in way of const.
93	Bursera simaruba	Gumbo limbo	6"	18'	18	254.34	To Be Removed - in way of const.
94	Bursera simaruba	Gumbo limbo	6"	18'	12	113.04	To Be Removed - in way of const.
95	Bursera simaruba	Gumbo limbo	11"	18'	20	314.00	To Be Removed - in way of const.
96	Bursera simaruba	Gumbo limbo	8"	15'	16	200.96	To Be Removed - in way of const.
97	Bursera simaruba	Gumbo limbo	6"	18'	18	254.34	To Be Removed - in way of const.
98	Bursera simaruba	Gumbo limbo	5"	15'	8	50.24	To Be Removed - in way of const.
99	Quercus laurifolia	Laurel oak	6"	15'	15	176.63	To Be Removed - in way of const.
100	Quercus laurifolia	Laurel oak	9"	20'	22	379.94	To Be Removed - in way of const.
101	Quercus laurifolia	Laurel oak	5"	24'	15	176.63	To Be Removed - in way of const.
102	Quercus laurifolia	Laurel oak	7"	20'	12	113.04	To Be Removed - in way of const.
103	Quercus laurifolia	Laurel oak	4"	18'	8	50.24	To Be Removed - in way of const.
103A	Quercus laurifolia	Laurel oak	3"	16'	8	50.24	To Be Removed - in way of const.
104	Quercus laurifolia	Laurel oak	5"	18'	8	50.24	To Be Removed - in way of const.
105	Quercus laurifolia	Laurel oak	8"	18'	20	314.00	To Be Removed - in way of const.
106	Quercus laurifolia	Laurel oak	5"	25'	8	50.24	To Be Removed - in way of const.
107	Bursera simaruba	Gumbo limbo	5"	18'	10	78.50	To Be Removed - in way of const.
	TOTAL SQ. FT. REMOVED					75,966.81	
Note:							
* = describes specimen trees (18" DBH or greater). Weeping Fig Tree is never considered a specimen tree.							


Revisions	
1	8.22.18 1st Issue
2	01/14/19 REPLY COMM.
3	02/4/19 DERM COMM.
	03/25/19 ZONING COMM.

PROPOSED NEW 50 UNIT APTS. COMPLEX
THE VILLAGE AT MIAMI GARDENS
3400 NW 191 ST.
MIAMI, GARDENS, FL 33056-2936

JCD ARCHITECT, Inc.
JUAN C. DAVID R.A. #0015344
Design & Development
LEED ACCREDITED PROFESSIONAL

Architecture
Interiors
Planning
Construction

1385 Coral Way, Suite 404 Miami, Florida 33145 Phone (305) 285-5443 Fax (305) 285-4330



Job No.
Date
Scale SHOWN



Seal
LA-6668869
Sheet No.
TD-1.1



Designs are subject to modification or change as required by actual measurements, standard industry practices in light of existing structural and other conditions, applicable bldg. codes, and the like. These plans are and shall remain the property of Mr. David and shall not be sold or reproduced without its prior written consent. Mr. David shall be notified of any changes req'd by actual measurements, etc. as aforesaid prior to submission of any phase for bid or construction.